


IMPORTANT SAFETY NOTICE

BLACK+DECKER® 18V Cordless Tiller/Cultivator

BLACK+DECKER® has determined that the assembly instructions originally included with the product can cause some consumers to attach the bottom portion of the Tiller/Cultivator upside down. Incorrect assembly can cause the blades of the Tiller/Cultivator to rotate toward the user, posing a potential laceration hazard.

This safety notice applies to **BLACK+DECKER®** Models **BETL18B-XJ**, **BETL1820L-QW** and **BETL1820L-GB** Cordless Tillers/Cultivators.



The model number “BETL18” is located on the underside of the upper handle of affected Tillers/Cultivators. The Tillers/Cultivators are orange and black and have the brand **BLACK+DECKER®** labelled on the handle and the bottom portion of the Tiller/Cultivator. If you are unsure if your Tiller/Cultivator is affected by this safety notice, or just want to ensure that it is assembled correctly, please view/download the updated assembly instructions to make sure your unit is assembled correctly.

If your Tiller/Cultivator is affected, STOP USING IT and either

1. Click [here](#), or
2. Scan the QR code to the right, or
3. Call +44 (0)1753 511234 (choosing option 1)

to obtain the updated assembly instructions.

