


# Important Safety Recall

## DEWALT Framing Nailers

The contact trip on some of the nailers may not operate properly, which may permit a nail to be ejected with only trigger actuation.

**DEWALT D51844 and D51845 Heavy-Duty 20° Full Round Head Framing Nailer**

**DEWALT D51822 Heavy-Duty 31° Clipped Head Framing Nailer**



**ONLY** nailers with the following date codes are affected:

200203, 200204, 200217, 200302,  
200304, 200308, 200315, 200325,  
200329, 200343, 200403, 200404,  
200406, 200407, 200412, 200413,  
200415, 200416, 200417

Check the top right side of your magazine to determine if it is missing the slot as shown in the images above

Check to see if the tab shown in the drawing at right is present on the contact trip. If yes, follow directions below.

If your nailer is affected, **STOP USING IT IMMEDIATELY**, and call DEWALT toll free at  
**1-866-397-3228**

between 8:00 a.m. and 4:30 p.m., Eastern Time, Monday through Friday,  
or at [www.DEWALT.com](http://www.DEWALT.com) for the location of a service center  
to obtain a free inspection and repair, if necessary.